

alpha micro

ISSG Newsletter

VOL. 5, NO. 1 JANUARY 1983

New AM-1000 Spare Parts Available


The Spare Parts for the AM-1000 Desktop Unit are now available from our Spare Parts/Logistics Department. One of the services provided by this area of the International Support/Service Group (ISSG) is that of spares forecasting. To enable you to better support your customers through an adequate spares inventory, we will construct a forecast tailored to your particular needs. For more information concerning this program, or to place a spare parts order, please contact Spare Parts/Logistics at (714) 957-6112.

SPK-01000-20	5 1/4" Mini-floppy Drive
SPK-01000-31	10MB 5 1/4" Winchester drive
SPK-01000-81	Controller circuit board for 5 1/4" floppy drive
SPK-01000-82	Controller circuit board for 5 1/4" Winchester drive
SPK-01000-91	100 Watt Switcher power supply

AM-1000 Spare Parts

SPK-01000-01	AM-167 CPU circuit board with VCR interface
--------------	---

For a complete listing of spare parts available, please contact the Spare Parts/Logistics department for a copy of the *Spare Parts Catalog*.



The AM-1000 Desktop Microcomputer

ISSG Newsletter Index - Volume 4

SUBJECT	NUMBER	PAGE
ALPHACARE - Alpha Micro Announces	7	1
ALPHACARE - Warranty Products	11	2
ALPHALINK - Uses for the AM-110	5	4
ALPHAPASCAL - Software Notes	5	12
ALPHASERV - Network Expands	3	2
ALPHASERV - Network Expands	5	2
ALPHASERV - Network Update	8	1
AM- 610 - Enhancements	2	8
AM-100/L - Adding additional AM-300 boards	11	2
AM-100/L - Boot PROMs Release	12	2
AM-100/L - General Discussion	7	3
AM-100/L - Notice to Users	9	3
AM-100/L - Warm Boot Tape Creation	7	12
AM-100/T and AM-120 - Jumpers for Use With AM-620	2	11
AM-1000 - Disk File Performance	9	1
AM-1000 - General Discussion	8	6
AM-1000 - Important Notice to Users	9	3
AM-1000 - Modification to use with AM-1001	12	6
AM-1000 - Terminal Cabling	11	8
AM-1000 Floppy Disk Drive - Maintenance	10	5
AM-1002 - Memory Expansion Module	11	3
AM-1010/1011 - Drive Preventive Maintenance	2	5
AM-1020/1021 - Installation	1	6
AM-1041 - Installation	1	6
AM-1050/1051 - Drive Filter Change	2	2
AM-1060/1061 - Motor Control Board Enhancement	2	7
AM-110 - Uses for AM-110	5	4
AM-210 - Delay Line Modification	9	3
AM-300 - Adding additional boards to AM-100/L	11	2
AM-300 - Interrupt for 2nd in Winchester Systems	5	4
AM-310/A	11	9
AM-410 - Phoenix Drive Retrofit Kits	11	2
AM-410 - Sector Counter Modification	12	4
AM-410,420,610 - Controller Board Modifications	3	11
AM-420 - ECC	11	6
AM-420 - Ground Wire Modification	12	5
AM-420 - Reset Line Modification	9	3
AM-420 - Winchester Error Code Reporting	9	4
AM-422 - Subsystem Main PCB Modification	4	12
AM-500 - Hawk Drive Absolute Filter Inspection	8	2
AM-600/T - General Discussion	10	1
AM-610 - Enhancements	3	2
AM-610 - Video I/O Level Modification	6	4
AM-621 - General Discussion	1	2
AM-621 - Streaming Tape Subsystem Maintenance	5	8
AM-700 - When to Use the MPC	5	6
AM-710,700 - Parity Command Error Messages	4	9
AM-720 - 512KB Memory Circuit Board	4	2
AM-900/A - Power Supply Modification	10	4
AM-965 - Front Panel Display Codes	8	12
AMOS - 4.6A Version Release Notes	6	10
AMOS MONITOR CALL - Generating a Shell Program	6	5
AMTEC - Communication/Information Link to ISSG	3	9
AMTEC - Update	2	1
BOOT PROMS - Reference Guide	1	7
COMPATIBILITY - Guide to Alpha Micro Prod. Compat.	8	10
CRC/ECC Conversion	11	6
CRT420 - Important Notice on Certification	10	6
CUSTOMER SERVICE - Defective Returns	1	1
CUSTOMER SERVICE - Addit. Hours for Dealer Contact	8	1
CUSTOMER SERVICE - Customer Contact Program	3	2
CUSTOMER SERVICE - Regionalized Account Reps	11	1
CUSTOMER SERVICE - Returned Goods	12	1
CUSTOMER SERVICE - Returned Goods Policy	1	1
DEVTBL - Configurations for Winchester Systems	3	6
ISSG - Direct Line Communication	7	2
MANUFACTURING - Consolidates Facilities	3	1

NEWSLETTER - Policy Changes	4	1
NEWSLETTER - Software Notes Consolidation	4	1
PACKAGING - Packaging Technology for Alpha Micro	6	1
PATCH (AMOSL) - 210DVR.DVR	11	11
PATCH (AMOSL) - 610DVR.DVR	11	11
PATCH (AMOSL) - AM100L.M68	12	11
PATCH (AMOSL) - AM120.M68	12	11
PATCH (AMOSL) - AMOSL.MON	9	7
PATCH (AMOSL) - AMSORT.SYS	10	8
PATCH (AMOSL) - BASORT.SBR	12	sup
PATCH (AMOSL) - COPY.LIT	12	sup
PATCH (AMOSL) - CRT410.LIT	12	9
PATCH (AMOSL) - CRT420.LIT	10	13
PATCH (AMOSL) - DSKANA.LIT	10	9
PATCH (AMOSL) - DSKPAK.LIT	11	10
PATCH (AMOSL) - How to implement a patch	9	4
PATCH (AMOSL) - INPUT.SBR	12	sup
PATCH (AMOSL) - ISAM.SYS	10	13
PATCH (AMOSL) - ISAM.SYS	9	8
PATCH (AMOSL) - ISMBLD.LIT	10	11
PATCH (AMOSL) - ISMBLD.LIT	9	8
PATCH (AMOSL) - ISMDMP.LIT	9	9
PATCH (AMOSL) - LABEL.LIT	10	12
PATCH (AMOSL) - PRINT.LIT	9	10
PATCH (AMOSL) - PRINT.SBR	12	sup
PATCH (AMOSL) - PTCH.LIT	9	6
PATCH (AMOSL) - RUN.LIT	11	12
PATCH (AMOSL) - RUN.LIT	12	10
PATCH (AMOSL) - RUN.LIT	9	10
PATCH (AMOSL) - SCNWLD.SYS	12	10
PATCH (AMOSL) - SET.LIT	9	11
PATCH (AMOSL) - SORT.LIT	10	14
PATCH (AMOSL) - SPOOL.SBR	12	sup
PATCH (AMOSL) - TRM.DVR	12	9
PATCH (AMOSL) - VUE.LIT	10	10
PATCH (AMOSL) - WRMGEN.LIT	9	11
PATCH (AMOSL) - XEBDVR.DVR	10	12
PATCH (AMOSL) - XLOCK.SBR	10	11
PATCH - Implementing a Patch	6	11
PATCH - Patch to AMI20.MAC	6	Sup
PATCH - Patch to AM310.MAC	6	Sup
PATCH - Patch to AX310.MAC	6	Sup
PATCH - Patch to BADBLK.PRG	6	Sup
PATCH - Patch to COMMON.MAC	6	Sup
PATCH - Patch to COPY.PRG	6	Sup
PATCH - Patch to CRT410.PRG	6	Sup
PATCH - Patch to CRT420.PRG	6	Sup
PATCH - Patch to DATA.PRG	6	Sup
PATCH - Patch to DSKCPY.PRG	6	Sup
PATCH - Patch to DSKPAK.PRG	6	Sup
PATCH - Patch to Dirseq.PRG	7	11
PATCH - Patch to FIXDVR.PRG	6	Sup
PATCH - Patch to FMT210.PRG	6	Sup
PATCH - Patch to MAP.PRG	6	Sup
PATCH - Patch to RUN.PRG AND RUNSML.PRG	6	Sup
PATCH - Patch to SERCH.SBR	6	Sup
PATCH - Patch to SYSTEM.MON	6	12
PATCH - Patch to VUE.PRG	6	14
PATCH - Patch to WRMGEN.PRG	6	Sup
PHOENIX DRIVE - Retrofit Kits	11	2
SERVICE CENTER - Repair Policy	8	1
SOFTWARE - Generating a Shell Program	6	5
SOFTWARE NOTES - AMOS Version 4.6A Release Notes	6	10
SOFTWARE NOTES - CRT610	5	12
SOFTWARE NOTES - Documentation Adj. DSS-10000-24	6	10
SOFTWARE NOTES - Implementing a Patch	6	11
SOFTWARE NOTES - Placement of QUEUE Command	5	11
SOFTWARE NOTES - Software Hints	5	12
SOFTWARE NOTES - VCR and Streamer Subsystems	5	12
SOFTWARE NOTES - WRMGEN and Alternate Track Tables	5	11
SOFTWARE RELEASE 1.0A	12	2

SPARE PARTS - Expedite Fee	10	1
STREAMER AND VCR SUBSYSTEMS - Software Notes	5	12
TRAINING - Schedule for August - December	8	3
TRAINING - Schedule for March - September 1982	3	2
TRAINING - Training Schedule Additions	7	3
TRAINING - Video Training Tapes	7	3
TRAINING - Video Training Tapes	5	1
TRAINING SCHEDULE - January-March, 1983	12	3
VCR - CRT Options	2	1
VCR - Choosing and Maintaining a VCR	6	2
VCR - Save and Restore Program	4	10
VCR - VCRSAV and VCRRES Programs	7	12
VCR AND STREAMER SUBSYSTEMS - Software Notes	5	12
WINCHESTER DRIVE - Rework for 60MB	12	8
WINCHESTER SYSTEMS - Boot Up Procedure	8	12
WINCHESTER SYSTEMS - General Discussion	1	9
Winchester - Important Notice on Certification	10	6
Winchester Drive - Error Code Reporting	9	4

ISSG Newsletter

Volume 5, Number 1 January 1983

Editor Susan Poyer

Contributors to this issue Don Altringer, Nick Maddocks

Copyright ©1983 by Alpha Microsystems.

Alpha Micro, AMOS, AlphaBASIC, AlphaPASCAL, AlphaLISP, AlphaSERV, AlphaVUE and AlphaACCOUNTING are trademarks of Alpha Microsystems.

The ISSG Service Newsletter is published monthly by the International Support/ Service Group. Please address all correspondence to: ISSG Newsletter, Alpha Microsystems, 17881 Skypark North, P.O. Box 18347, Irvine, CA. 92713.

Alpha Micro has checked the information contained in this newsletter and believes it to be accurate at the time of publication. However, readers should independently determine that any information used works correctly on their system and is appropriate for their application.

ISSG Telephone Numbers

Customer Service (714) 957-6076

Technical Education (714) 957-6076

System Support (714) 957-0392

Spare Parts/Logistics (714) 957-6112

AMTEC

(1200 Baud Bell 212A) (714) 545-6128

AMTEC

(300 Baud Bell 103J) (714) 957-0697